

Walt Vinoski
1-724-713-1753
walt@vinoski.com
walt@vinoskiengineering.com

1

Vinoski & Associates, Inc.

LATENT DEFECT DESIGN REVIEWS

ROOT CAUSE INVESTIGATIONS

INSURANCE CLAIM SUPPORT

DEVELOPMENT, EPC, LTSA

Offices across the USA
& London, Great Britain

Resources USA & UK

2

- ▶ Energy, Power, Transmission, Machinery Support
 - ▶ Locations: Pittsburgh, Pennsylvania, Arizona, Arkansas, California, Florida, Illinois, Massachusetts, Oregon, Texas, Wisconsin, Wyoming,
 - ▶ Dozens of Engineers / Specialized Experts
 - ▶ Architect-building, chemical, civil, controls, electrical (generators, transmission & distribution AC & DC), fire investigation, large rotating equipment, lightning experts, marine, mechanical, nuclear, solar (photovoltaic, thermal), steel & aluminum mills, turbines (combustion, steam, solar, & wind systems), reciprocating engines, and vibration expertise.
 - ▶ On-shore and limited off-shore experience
 - ▶ National Association of Fire Investigator Certified
 - ▶ 3 metallurgists
 - ▶ Lightning experts
 - ▶ Civil & Architectural engineers

Power, Energy, and Transmission

- ▶ Our Claim Expertise, Accurate RCAs, for LM, LMS, F, G, H, & J Technologies.
 - ▶ O&M, repairs, design, owner's engineers, power purchase agreements, service contracts, construction, functional and performance testing, and failure modes.
 - ▶ Nuclear, coal, natural gas, hydrogen, LNG, hydro-electric.
 - ▶ Gas turbines, steam turbines, reciprocating engines & generators, pumps, mills, etc.
 - ▶ Jet engines, aerospace engines, aerospace diesels. Weapon systems and other devices
 - ▶ Transmission, distribution, substations, switchyards, high-voltage inverters
 - ▶ "Green" biomass, wood, methane, wind, solar thermal & photovoltaic
 - ▶ Ancillary equipment: SF6 breakers, transformers, synchronous condensers, black start capabilities, boilers, HRSGs, CEMS
 - ▶ Pipeline, distribution, transmission, scrubbing, & delivery
 - ▶ Civil and structural design, faults, demolition, and restoration work.
 - ▶ Explosives demolition, errors, risks, and monitoring.

Root Cause Analysis

- ▶ RCA investigations, allowing the insurer and the insured to find the actual root cause and who was at fault.
 - ▶ The OEM “determined” that the operator was running the HP Turbine too hot and provided a multi-million repair option. Insurers requested VAI investigate
 - ▶ VAI found the failed HP Impulse Wheel was improperly repaired.
- ▶ Latent design defects expertise
 - ▶ For H & J Hot Gas Path components.
 - ▶ For Hydrogen Burners
 - ▶ For High Pressure Compressor damages
 - ▶ Blading design short-comings, incorrect root design applications, etc.
 - ▶ Steam turbine failures including water induction, windmilling, seal failure

Sand and dust do not destroy bearings



Cause of Accident / Death

- ▶ VAI expertise in determining
 - ▶ Cause of accidents and
 - ▶ Cause of death.
- ▶ Providing legal support
- ▶ Modeling
- ▶ Visual support
- ▶ Accident investigations

Lab Product Liability Testing

6

- ▶ Wind turbine blading
- ▶ Electrical Testing of Appliances
- ▶ Modeling of Transformers and electrical apparatus.
- ▶ Testing and Failure Modes Analysis
- ▶ Design defects
- ▶ Legal support
- ▶ Root cause
 - ▶ Lab work
 - ▶ Field work



Confidential & Proprietary Information .
Please do not distribute outside of your company.


Value Added

- ▶ Columbia, S.A. 125 MW hydro unit, with seven major arc-flash damages to the stator, due to the loss of a grounding line.
- ▶ The OEM stated that it would take 18 to 24 months to deliver a new stator.
- ▶ We provided an immediate repair solution,
 - ▶ Getting the unit online in two months safely achieving 119 MW of the 125 MW.
 - ▶ Gave ample time to the utility to install a 135 MW upgrade 5 years later.
 - ▶ No BI loss;
 - ▶ PD less than the deductible.

Confidential & Proprietary Information.
Please do not distribute outside of your company.

Aerospace, Aviation, Jet Propulsion, etc.

- ▶ Claim Damage.
- ▶ Reparability.
- ▶ Replacement Valuations.
- ▶ Salvage



Confidential & Proprietary Information .
Please do not distribute outside of your company.

OEM “Cannot determine the Root Cause”

- ▶ With a quick on-site investigation.
 - ▶ A focused VAI metallurgical examination.
 - ▶ A quick review of the commissioning records.
- ▶ The cause was determined to be poor execution in commissioning by the OEM.
- ▶ Warranty – Poor OEM Workmanship.

Confidential & Proprietary Information.
Please do not distribute outside of your company.



4th Stage Tip Liberation from poor commissioning on fuel oil.

SF6 Breaker Damage

- ▶ SF6 Breaker trips out and reported as damaged
- ▶ Plant reports fire or electrical arc-flash damage.
- ▶ A handkerchief removed the oxide layer (black)
- ▶ OEM states 6 months replacement for B.I.
- ▶ Site inspection of the SF6 Breaker reveals that the seals were damaged compromising the hermetic seal due to a lightning strike.
- ▶ The plant could only run one unit. VAI told the plant that the protection circuitry worked and that they did not need this set of SF6 Breakers – so by-pass them with a cable.
- ▶ While that idea was first thought to be hazardous and unsafe, the OEM explained it was indeed safe. The by-pass was installed and the SF6 Breaker repaired with “spare parts”
- ▶ Downtime reduced to 10 days!


Confidential & Proprietary Information.
Please do not distribute outside of your company.

10



550 MW STG Loss of DC Power

- ▶ The DC Power for the Lubricating Oil System Failed resulting in no lubricating oil during a coast down.
- ▶ Bearings, Seals, and Blading were damaged during the Event.
- ▶ VAI design review showed multiple failure modes and effects.
- ▶ Conclusion in VAI report stated: “Unless at least two of recommended controls changes are implemented, there will be another Loss of Lube Oil Event on this turbine within a year.”
- ▶ There was another loss before that year ended.
- ▶ The insurers asked us to do an EPC Design Review, we listed several un-safe modes of failure. This design was used in 6 other power plants in South America.



6,500 HP Motor- Red Gear-Ball Mill

- ▶ Three years of failures on an old ball mill with rebuilt motors.
- ▶ Neither the motor manufacturer or other parties could determine the root cause of the motor failures, including cracked spider welds.
- ▶ VAI was called upon to analyze all the vibration data, the shop motor damage, repairs and other documentation.
- ▶ Within a few days VAI determined a torque issue Rick O'Mahony determined that the damage, as supported by our vibration expert, were occurring during startups and Rick declared that one of the soft-start liquid resistors was the problem.
- ▶ After VAI's findings were conveyed to the plant; the plant confirmed it to be true. It continues running to this day without any downtime.



OEM Blames Owner for Damaging H.P. Impulse Wheel

13

- ▶ Vinoski & Associates, Inc. – Led by Dan Kelso with the support of our metallurgist Joe Daleo prove the OEM compromised the blades, making them susceptible to steam admission excitation and subsequent failure.
- ▶ The claim gets turned over to the OEM, saving the insurance company millions.




OEM blade cut back too far.



Changes excitation frequency, & blade liberates

VAI FEA model proves the excitation



6 MW STG Rotor Liberation

- ▶ STG remote controls were not working.
- ▶ Cannot reduce load as the admission valves will not close.
- ▶ Plant personnel hit the E-stop, which is just another switch for the remote control. The valves get the same signal to close but do not. With the E-stop the generator main breaker opened, resulting in a 6,800 rpm overspeed failure.
- ▶ This happens frequently. What should have occurred is to manually close the turbine steam header root valve as quickly as possible.



LM6000 Old Compressor Blade Design

15

- ▶ OEM upgrades compressor blade root design
- ▶ The timing of the upgrade requirement is not clear
- ▶ 5th Stage blade liberates causing downstream damage
- ▶ As normal, the “repairs” include wear, and damage from previous incidents.
- ▶ Claim gets greatly reduced.



501 J CTG 330 MW

- ▶ Builders All Risk – Contamination of steam cooled transition piece(s).
- ▶ OEM initially wanted to replace 8 TPs and inspect 12.
- ▶ We participated in the TP inspections, at night and on the weekend. OEM declared 5 had to be inspected for contamination, although no contamination was visible – only water marks (dried deposits).
- ▶ We had the OEM inspect their brand-new replacement TPs to show them that after welding they all are water washed and then dried – and all had the same water marks.
- ▶ Only two TPs required a water flush.
- ▶ The final claim damage was appropriately reduced to maintenance activities.



Wind Turbine Generator

17

- ▶ Latent Design Defects:
 - ▶ Mechanical
 - ▶ Electrical
 - ▶ Controls
 - ▶ Materials/Fabrication
 - ▶ Earth-grounding & Lightning Protection
- ▶ Wind-farm Electrical Distribution
 - ▶ Design Errors
 - ▶ Protection Errors
 - ▶ Transmission System Weaknesses



Solar Energy Thermal/Photovoltaic

18

- ▶ Latent Design Defects
- ▶ Mis-managed Upgrades
- ▶ Operational Damages
 - ▶ Distribution
 - ▶ Electrical
 - ▶ Controls
 - ▶ Materials/Fabrication




Confidential & Proprietary Information.
Please do not distribute outside of your company.

250 MVAR Synchronous Condenser

19

- ▶ These devices are essentially motor/generators that are used to regulate VARS.
- ▶ New units with only 4,000 hours developed rotor pole cracking
- ▶ An RCA is underway, to clarify a manufacturing problem, in that the original design allowed too great of stress risers.



Confidential & Proprietary Information.
Please do not distribute outside of your company.

250 MVA Transformer - Derailment

- ▶ Superficial Damages
- ▶ OEM rejected the unit, per the policy.
- ▶ OEM stated they could not economically repair the unit.
- ▶ The damaged transformer was later purchased for scrap value and then repaired.




Argentina, S.A. Transmission Distribution

- ▶ Underground 230kV Line arc-flash
- ▶ \$17 million in repairs expected.
- ▶ New repairs to a 45-year paper insulated line induced secondary cracking and compromised the integrity of the paper insulation (causing cracking).
- ▶ It was less expensive to pull 92,500 feet of all new XPLE cable
- ▶ Our repair plan succeeded to repull all new cable for \$3 million.





Compressor Clashing (“Surge”)

- ▶ OEMs blame operators for their loss.
- ▶ Clashing often is based on “surge conditions”
- ▶ Clashing is due to the physical flexing of the outer casing.
- ▶ At the right are two clips from a modal model.



Clashing viewed with reading glasses

23



Differential Cooling & Non-uniform Thermal Expansion cause clashing.

Combustion Turbines: G, H, & J Technologies.

Cooling issues remain, not an operations problem.

24



Confidential & Proprietary Information .
Please do not distribute outside of your company.

Experts

25

- ▶ Walt Vinoski – Siemens-Westinghouse & MHI CTG, Steam Turbine & General Power plant, FEMA
- ▶ David Kalmanovitch (UK-based) – Metallurgist, Turbine Hot Gas Path and Boiler corrosion expert
- ▶ Paul Markham (UK-based) Power Engineer, conventional turbine-generators, renewables
- ▶ Georg Nauman – design, fire/water piping, structural, modeling, loading.
- ▶ Wendall Moulder – Nuclear, Power, Gas/LNG Startup Boiler Expert. UK, South Africa, Mexico, Canada, Indonesia, Thailand, and Singapore.
- ▶ R. “Bucky” Croushore. Civil Engineer – Power plant structural steel. Bridge damages repairs, designs, and claims reviews.
- ▶ Dudley Green – GE Combustion Turbine expert, general steam turbine expert
- ▶ Mike McNeil – Electrical Engineer – Apparatus, Root Cause Analysis protocols, Fault Tree Analysis, Life-cycle Planning
- ▶ Rick O’Mahony – Electrical, Generator designer/repairs, switchgear, transformers, and grounding. Wind Turbine experienced
- ▶ Jack Bahnak – Electrical, Transformers, Electrical apparatus, turbines, wind turbines, & Product Liability Testing
- ▶ Kim Eiss – electrical generator expert
- ▶ Rick Johnston – Chemical Eng. Layer bonding and defect issues
- ▶ Dr. Fuchs (USA), Dr. Kalmanovitch (London), - Materials, bonding, manufacturing.
- ▶ Dan Kelso, turbomachinery, bearing designer, wind, general plant design, maintenance.
- ▶ Helmut Nauman – Steam and gas turbine designer
- ▶ Robert Shallenberger, materials engineer – quality controls
- ▶ Dr. Uman – Earth grounding and lightning expert
- ▶ Mark Bennett – Startup and O&M expert for coal and combustion turbines.
- ▶ Joe Jaskulski – certified fire inspector
- ▶ Dick Johnston – GE & P&W aero derivative turbine design engineer
- ▶ Ralph Leidy. Powerplant O&M Expert, Turbine Machinery Operations, and Maintenance expertise.
- ▶ Justin Jeffcoat. Crane, rigging, and lifting expert.
- ▶ Gene Borrows – Wind and power plant startup and construction manager.
- ▶ Robert Bizzak. NRC designer, piping and rupture expert.
- ▶ Various Controls Experts, Process Engineers, Civil Engineers, and Construction/O&M Experts